

MOUNT LAUREL TOWNSHIP

Municipal Utilities Authority

1201 SOUTH CHURCH STREET • MOUNT LAUREL, NEW JERSEY 08054

www.mltmua.com

PHONE (856)234-0062 • FAX (856) 866-1092

Lead Service Line Replacement Program – Annual Report 2021

The New Jersey Department of Environmental Protection (NJDEP) requires that a public water system complete a Lead Service Line Replacement Report (LSL). A component of this rule is the need to identify lead service lines (NJ defines lead service line as any part that is lead or galvanized steel) so they can be identified for replacement. The Mount Laurel Township MUA's water system is currently in compliance with and is required to meet all aspects of the Lead and Copper Rule.

Currently there are no service lines identified in our system which are made of lead or other materials containing lead, which would require replacement according to law; Our reports to NJDEP indicate this. During the process of performing system maintenance or service call response, our operators continually collect data related to the service line material encountered when comparing to known materials. In the event any suspect material is found we will update our records and follow up according to the current regulations to address the replacement of the service line with the owner as required.

Our water system, like others in New Jersey, ***is not*** the owner of a property's service line (pipe connecting property to the water main); the service line is owned by the property owner.

Service Line Inventory Report
 New Jersey Department of Environmental Protection
 Division of Water Supply and Geoscience - Water System Operations Element



I. System Information

Water System Name:	Mount Laurel MUA
PWSID Number:	324001

II. Contact Information for Owner/ Licensed Operator of Record Completing the Form

Contact Name:	Charles Bernheimer
Contact Title:	Operations Director
Contact Phone:	(856) 638-1290x201
Contact Email:	cbernheimer@mltmua.com

III. Inventory Information

Owner of Service Lines: System Property Owner Both

	Selection	Number of sites
I. Lead	<input type="checkbox"/>	
II. Galvanized	<input type="checkbox"/>	
III. Lead gooseneck, pigtail, or connector	<input type="checkbox"/>	
IV. Lead Status Unknown	<input type="checkbox"/>	
V. Non-lead	<input checked="" type="checkbox"/>	17967

# of LSLs to be replaced/identified: 0	# of LSLs to be replaced annually: 0
Total # of service lines in PWS: 17967	# of known LSLs 0

IV. Inventory Availability

This inventory has been made publicly accessible by:

<input checked="" type="checkbox"/>	If 3,300 customers or greater: Posting the inventory on my water system's website	Website: www.mltmua.com
<input type="checkbox"/>	If under 3,300 customers: Posting the inventory in a publicly accessible place, if a website is not available	Inventory is available via:

V. Certifications

By submitting this form, I have verified and certify the information listed in this form is true and accurate to the best of my knowledge and belief.

_____ Charles Bernheimer Water System Owner or Licensed Operator Name	_____ 1/19/2021 Date	_____ Operations Director Title (if WS Owner)
---	----------------------------	---

